# Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Wednesday, November 20, 2019 5:10 PM

**To:** CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO);

Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria ; Harbour Master- Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine

Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Rahman@tsb-bst.gc. ca (Zillur.Rahman@tsb-bst.gc.ca)

**Subject:** 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

**VANCOUVER - ALLISION - INITIAL** 

<b>GENERAL DATA</b>	- MARINE OCCU	RRENCE REPOR	I				
VESSEL NAME/O	CALL SIGN/REG :	OCEAN TRADER 1/9V3626					
JRCC INCIDENT #:		V19-	PRIORITY:	- BRC	)ADCAST: -		
INCIDENT START TIME:		20/Nov/2019 1638 PST					
INCIDENT END T	ΓIME:	Click here to e	nter a date. Click h	ere to enter tex	t.		
NATURE OF INC	IDENT:	ALLISION					
PERSONS ON BO	DARD:		LOSS OF LIFE:	No			
POSITION (GPS	/ GEOGRAPHIC):	VANCOUVER I	HARBOUR – ALLIAN	CE GRAIN EAST			
**************************		49 17.21.1N	123 04.43.2W				
VESSEL PARTICU	<u>JLARS</u>						
LOA:	224.94M	TYPE:	BULK CARRIER	OFFICIAL#	4003050		
MMSI:	564252000	GRT/DWT:	39738TLP/76596T	IMO:	9362217		
DESTINATION:	VANCOUVER, BC	LAST PORT:	***************************************	CARGO:			
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SAT PHONE:			
ADDITIONAL VE	SSEL DETAILS:	***************************************		A	***************************************		
SITUATION DET	AILS						
SITREP/RESOLU	***************************************	TRADER 1 COL GRAIN EAST. PILOT REPORT	LIDED WITH THE D	OCK WHEN BER	REPORT THAT THE OCEAN THING AT ALLIANCE HE PADDING ON THE		
INTENTIONS OF	MASTER:	DENTIT WAS D	MINDED. JIII OII	121144132 114 000			
ON-SCENE ASSIS		***************************************					

POLLUTION/NAV HAZARD:	NONE REPORTED		
WEATHER DETAILS			
VISIBILITY:	GOOD	WIND (KNOTS):	LIGHT
SEA STATE:	CALM	TIDE/CURRENT:	
ALERT LIST (NAME AND DATE/TI	ME OF VERBAL ALERT)		
CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE)		***************************************	
TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSE	20/Nov/2019 164	19 PST	
VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)	20/Nov/2019 164	15 PST	
MCTS OFFICER:	JN		
MCTS WATCH SUPERVISOR:	JN		
VICTORIA MARINE COMMUNICA			
CANADIAN COAST GUARD/GOV			
SUPERVISOR.VICTORIA@INNAV	<u>GC.CA</u> /TEL: 250-363-6	333   1-800-661-92	02 / FAX: 250-363-6556
Righar as and Oceans Réchas and: Canada Canada	93"\$		
Canaman Garza dis av Caas, Buara dana barna	1		<sup>®</sup> Canadä

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

# Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Wednesday, November 20, 2019 6:18 PM

To: CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO);

Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria ; Harbour Master- Victoria Assistant ; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine

Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur. Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca)

'colley@colleywest.bc.ca'; 'oceantrader1@amosconnect.com'

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

**VANCOUVER - ALLISION - UPDATE #1** 

## UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

Cc:

# Israr Waheed

Senior Marine Inspector
Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT				
VESSEL NAME/CALL SIGN/REG :	OCEAN TRADER 1/9V3626			
JRCC INCIDENT #:	V19- PRIORITY: - BROADCAST: -			
INCIDENT START TIME:	20/Nov/2019 1638 PST			
INCIDENT END TIME:	Click here to enter a date. Click here to enter text.			
NATURE OF INCIDENT:	ALLISION			
PERSONS ON BOARD:	LOSS OF LIFE: No			
POSITION (GPS / GEOGRAPHIC):	/ANCOUVER HARBOUR – ALLIANCE GRAIN EAST			
	49 17.21.1N 123 04.43.2W			

VESSEL PARTIC	ULARS				
LOA:	224.94M	TYPE:	BULK CARRIER	OFFICIAL#	4003050
MMSI:	564252000	GRT/DWT:	39738TLP/76596	IMO:	9362217
DESTINATION:	VANCOUVER, BC	LAST PORT:		CARGO:	
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SAT PHONE:	
ADDITIONAL VE	SSEL DETAILS:			•••••••••••••••••••••••••••••••••••••••	
SITUATION DET	AILS				
SITREP/RESOLU		TRADER 1 COI GRAIN EAST. PILOT REPORT	LLIDED WITH THE D	OCK WHEN BER	REPORT THAT THE OCEAN RTHING AT ALLIANCE THE PADDING ON THE OD CONDITION.
INTENTIONS OF	MASTER:				
ON-SCENE ASSIS	STANCE:				
POLLUTION/NA	V HAZARD:	NONE REPORT	ΓED		
WEATHER DETA	<u>VILS</u>				
VISIBILITY:		GOOD	WIND (KN	OTS): LIGH	IT
SEA STATE:		CALM	TIDE/CURI	RENT:	
ALERT LIST (NA	ME AND DATE/TI	ME OF VERBAL	ALERT)		
CCG-W ER DUTY OF (IF POLLUTION PRESENT OR F					
TC MARINE SAFETY	OFFICER OR LOSS OF LIFE ON ANY VESSEL		19 1649 PST		
VANCOUVER HBR N	********************************		19 1645 PST		
MCTS OFFICER:		JN			
MCTS WATCH S	UPERVISOR:	JN			
CANADIAN COA	INE COMMUNICA AST GUARD/GOVE CTORIA@INNAV.	RNMENT OF CA		)-661-9202 / FA	X: 250-363-6556
Estatas an Caraca Caraca Caraca Casa Carac		9975			®Canadä

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

# Rear, Scott

From: OCEAN TRADER 1 - MASTER < oceantrader1@amosconnect.com>

Sent: Thursday, November 21, 2019 3:52 AM

To: Supervisor. Victoria

CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO); Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria; Harbour Master- Victoria Assistant; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional IOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur. Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca); 'colley@colleywest.bc.ca';

Operations New York (ULTRABULK); Norden/Bulk Operations; S.Ganesh; Synergy Group Operations; Capt. Anand Vasanthan ADPA; Niju Kurian JK Tech Supt; Synergy Oceanic

Insurance; Synergy Oceanic QHSE; VGOceanTrader1

Subject: Re: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #1

Attachments: RA Sailing Vessel to discharge port (China) with dent on hul.pdf; Incident Report 20 Nov

19.pdf

**Importance:** High

Dear Sir,

Good day.

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

SMT: UTC-8

E-Mail:oceantrader1@amosconnect.com

FBB Phone:+870-773151881 (Cabin + Bridge) Sat C:456425212 MMSI :564252000

NOTE: Vessels incoming Email size is restricted to Max 1 MB File.

<sup>\*</sup>For urgent matters please notify via Sat-C or follow up by phone.

<sup>\*</sup>Ship's e-mail is not monitored continuously.

----

From: Supervisor. Victoria

Date: Thu, 21 Nov 2019 12:18 +1000 Msg: AMOS-1451950100

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - UPDATE

#1

To: CBSA Operations

To: Ottawa NCC-CCN [DFO]

To: CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-Aides

To: CCG-W JRCC A/Supervisor

To: CCG-W Manager Marine Aids Coastal

To: CCG-W Marine Aids Coastal Officer

To: CCG-W ROC - Alerting

To: CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca)

To: Clinton. Rebeiro@tsb-bst.gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca)

To: DFO Radio Room - Aldergrove

To: Environment Canada (ec.cnue-neec.ec@canada.ca)

To: Glenn Budden (Glenn.Budden@tsb-bst.gc.ca)

To: Harbour Master - Vancouver

To: Harbour Master-Victoria

To: Harbour Master-Victoria Assistant

To: Jeff Brady

To: Victoria JRCC [DND]

To: Kevin, Carrigan

To: Lisa McCulloch

To: MCTS Regional Office

To: MCTS-W REGIONAL SUPERINTENDANT (AS)

To: Mohan Raman (Mohan.Raman@tsb-bst.gc.ca)

To: Victoria MSOC West [DFO]

To: Pacific Pilotage Authority (info@ppa.gc.ca)

To: RCMP West Coast Marine Services

To: RITA CIAMMAICHELLA

To: Stroud, Chad

To: Sue Pickrell

To: SITCEN [TC]

To: TC Marine Safety - Vancouver

To: TC SITCEN alternate

To: Transportation Safety Board - Pacific

To: Zillur. Rahman@tsb-bst. gc. ca (Zillur.Rahman@tsb-bst.gc.ca)

Cc: 'colley@colleywest.bc.ca'

Cc: 'oceantrader1@amosconnect.com'

### UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

Master to confirm there is no ingress of water through hull.

Answer: Confirmed, no water ingress of water through hull.

Provide incident report including risk assessment.

Answer: Please see the attached.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

# All communications and rectification report to be sent to MCTS. Regards Israr Waheed Senior Marine Inspector **Cargo and Examination Services GENERAL DATA - MARINE OCCURRENCE REPORT** VESSEL NAME/CALL SIGN/REG: OCEAN TRADER I/9V3626 JRCC INCIDENT #: V19-PRIORITY: **BROADCAST: INCIDENT START TIME:** 20/Nov/2019 1638 PST **INCIDENT END TIME:** 20/Nov/2019 1612 PST (All lines made fast at AGT-East) Click here to enter a date. Click here to enter text. **NATURE OF INCIDENT: ALLISION** PERSONS ON BOARD: 21 crew including Master / 1 POB LOSS OF LIFE: NO

POSITION (GPS / GEOGRAPHIC): VANCOUVER HARBOUR - ALLIANCE GRAIN EAST 49 17.21.1N 123 04.43.2W

49 17.21.1N 123 04.43.2W
VESSEL PARTICULARS
LOA: 224.94M
TYPE: BULK CARRIER
OFFICIAL # 400305
MMSI: 564252000
GRT/DWT: 39738/76596T
IMO: 9362217
DESTINATION: VANCOUVER, BC
LAST PORT: FSD-4, VANCOUVEER, BC AGT-East, VANCOUVEER, BC
CARGO: CMP=35843.4850 MT 2 ROW MALT BARLEY=23,213.820 MT
FLAG: SINGAPORE
OWNER/AGENT CONTACT: GLOBAL UNITED SHIPPING (S) PTE LTD/ COLLEY WEST SHIPPING LTD +1 (604) 6873733
SHIP PHONE/SAT PHONE: +870-77315188

ADDITIONAL VESSEL DETAILS: LOADED CONDITION.

# SITUATION DETAILS SITREP/RESOLUTION: DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST. PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION. INTENTIONS OF MASTER: VERIFY THE EXTENT OF DAMAGE, CONTINUE MONITORING OF WBT'S AND CH-BILGES. REQUEST ASSISTANCE AND RECOMMENDATION/S FROM THE ATTENDING SURVEYOR/S. **ON-SCENE ASSISTANCE:** REPORTED TO GOOD OWNERS AND AGENTS (COLLEY WEST) FOR VERBAL REPORT. **POLLUTION/NAV HAZARD:** NONE REPORTED **WEATHER DETAILS** VISIBILITY: GOOD WIND (KNOTS): LIGHT **SEA STATE: CALM** TIDE/CURRENT: ALERT LIST (NAME AND DATE/TIME OF VERBAL ALERT) CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE) TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEL)

20/Nov/2019 1649 PST

# VANCOUVER HBR MASTER

(ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)

20/Nov/2019 1645 PST

MCTS OFFICER:

JN

MCTS WATCH SUPERVISOR:

JN

**VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES** 

CANADIAN COAST GUARD/GOVERNMENT OF CANADA

SUPERVISOR.VICTORIA@INNAV.GC.CA<mailto:SUPERVISOR.VICTORIA@INNAV.GC.CA> /TEL: 250-363-6333 | 1-800-661-9202 / FAX: 250-363-6556

[cid:image001.png@01D35022.D7AF5AE0] [cid:image002.png@01D35022.D7AF5AE0] [cid:image003.png@01D35022.D7AF5AE0]

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca<mailto:Supervisor.Victoria@innav.gc.ca>

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

## HAZARD IDENTIFICATION AND RISK ASSESSMENT FORM

S.No (Synergy / Vessel / Year/ S.no):	SOPL / OT1 / 2019 /NOVEMBER/001
Vessel Name / Office Name:	OCEAN TRADER I
ocation:	In Port
Date of carrying out RA:	20-11-2019
expected Date and Time of activity:	20-11-2019
xpected duration of the activity:	
Office Approval obtained	Yes
Risk Assessment Reviewed On:	20-11-2019
sset Activity:	Others
Asset Condition:	Loaded
tisk Assessment required for:	Hazardous activity
vature of Work:	Sading Vessel to discharge port (China) with dent on hull
rea of Work	ship's stability and water integrity
oncurrent activity affecting main activity	MIL
	Injury - Checklist (Contingency Manual Ch.5.17.11)
Vorst Case Scenario and (Contingency Manual Ch05: Response	Hull Breach - Checklist (Contingency Manual Ch 5.17.5)
Measure Checklist)	Collision / Allison - Checklist (Contingency Manual Ch 5.17.4)

#### Notes.

- 1 Sample Database to be referred, while performing a task, to review and amend the sample RA to a job specific RA
- 2. Level II risk assessment to be made for new or unfamiliar tasks (not already covered in our SMS). See section 8.4.1/8.4.2.
- 3. Office approval needed for Level II Risk assessment only if the residual risk remains HIGH or VERY HIGH after further risk control measures. Only work sheet 'information input' & Pg. 1 Table' is to be sent to office for approval.
- 4. Job scope has to be systematically breakdown and sequentially placed in 'Activity Step' section.
- 5 Control measures that are not already included in the company procedures are to be reflected in the 'Further risk control measures'
- 6. Worst case scenario are the measures (checklist) that are given in the contingency manual that would control the risk from further escalating

<sup>\*</sup>Refer to instructions page for differentiation between on RA I and RA II

# HAZARD IDENTIFICATION AND RISK ASSESSMENT FORM

	Hazard Review Date	21 NOV. 2219	21 MV 349	1 21 NW 247	4 MV. 2019
	Nerne / Date and Signature (PIC-Ensuring the control measures are in piece)	10 A 100 ERA 22/11/2017	21/11/2014	Manual Polar	Total 2019
Risk	Residual Risk	(0.51) <del>(0.</del> 555)		1000	toy
Modified Risk	Consequences	SERIOUS HARM	SERIOUS HARM	SERIOUS HARM	MODERATE HARM
ž	Likelihood	Remote	Remote	Remote	Unlikely
	Further Risk Control Measures	Regular sounding of the Compartment	Inspection by Class prior sailing.		Monitoring vessel from Office and providing additional weather updates.
7	Residual Riek	Medium	Medium		Medium
Existing Risk	Consequences	SERIOUS HARM	SERIOUS HARM	SERIOUS HARM	MODERATE HARM
Ex	Likelihood	Unlikely	Unlikely	Remote	Likely
	Recovery Messures (Messures in place to reduce the consequence if insolverent event take place; eg. Placing of fire extinguishers, stretchers, Rescue davits etc.)	Comply with Emergency Checklat for hull breach. Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance.	Comply with Emergency Checklist for hull breach. Refer Emergency contact list, call for external assistance
	Existing Control Measure (Control measures in place to prevent occuring of inadverent event due to hazard.)	Dent on the Hull visually Inspected and adjacent compartment sounded Ascertained no cracks or water ingress. SF/BM within limits.	Monitoring compartment by sounding, SF/BM within limits. Weather routing.	Crew briefed. Contingency drills on hull breach planned	Weather routing guidance followed of Speed reduction and course alteration to avoid areas of heavy weather
	Consequence (Possible outcome from inadvertent event because of mention hazard)	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage	Loss of Stability, Cargo damage
	Hezards associated with each activity step. Hezard identification shall focus on its affect to people, environment, asset & reputation)	a Bessed Bujing sea Bujing a sea Mujing to a sea sea judi sea	Crack developing during the voyage	Crew unprepared for Contingency	Adverse weather
	Activity Step (Job Scope break down and placed sequentially)	Sailing Vessel to discharge port (China) with dent on hull	Saling Vessel to discharge port (China) with dent on hulf	Sailing Vessel to discharge port (Cnina) with dent on hull	Saling Vessel to discharge port (China) with dent on hull
	£ 2	, ·	N 2	<i>x</i> =	32



Approved By

Rank

HAZARD IDENTIFICATION AND RISK ASSESSMENT WERE DISCUSSED / BRIEFED TO THE FOLLOWING CREW MEMBERS ( Applicable to level 2 RA only)

Task Commencement Time Risk Assessment done by

Signature

Rank

Edition No.1 / Rev.No.0 Date: 07-Jan-2019

SF 23

# INCIDENT REPORTING

Synergy Group

ACCIDENT / DAMAGE REPORT (In case of injury is reported, please use injury reporting form too.)

Ref. No.	(Eg DEH-01/09)	Date of I	report: 20 Nov. 2019	)
n case an injury also involved	! please add injury report a	also (Form SF-06) Ref.No	NA	
AA, Name Of Ship:	Ocean Trader 1	BB. Type of ship	Bulk Carrie	er
CC. Date of Damage	Nov 20, 2019	DD. Time :	1550 LT	
E. Ship Status (At Se port ( Pis mention na	a / Port/ Anchorage	FF. Makeup OI	21 Crew incl Mast	er and 1 Pilot
ancouver, Canada GG. Related Departme Deck / Engine / Cateri				
1533 LT = Aft lug ma 1550 LT= Vessel hit hull in way of Hatch r 1600 LT = First line A 1612 LT = All Lines r 1615 LT= Forward & 1624 LT= Pilot Off 1630 LT= Initial notifi	pard, SBE Pilot Exchange Into Pilot Exchange Pilot		the incident !nspec	
Any regulatory reports of yes who will make J. Possibility of recursively Unlikely	? Office   rrence (Refer HSM Ch 0) Un Likely   (Ref Ch.9 Ship Manager)	Ship    Ship    Very Likely		
L. Consequence	· · · · ·			
Fatality / Disability Additionally send Injury R	lengt form SE-061	Environmental Damage	, Œ	
	Spart Form SP-00)	Commercial loss (loss of hire		
Personal Injury  Additionally send Injury R	Report Form SF-06)	Reputation loss / Media expo Third party damage (Other ves		
ial Synangy		SF-05		Rev
		Page 1 of 5		7-31

Orig Copy : Vessel File

Page 1 of 5

STRER OL AC		DENT REPORTING	Synergy Group
* In case	of injury is n	reported, please use injury reporting form too.)	
© Cwn yesel hull damage		Shore structure &Carpo ashore or on i	other shin.
Win vessel machinery damage		Other losses (Please specify)	1 Shore fender damaged
Own vessel cargo damage		Time delay to the vessel	
Own vessel-other property damage		Man hour lost	



# INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

In case of injury is reported, please use injury reporting form too.)

M. Cause Analysis (Write descriptively)	
Direct cause (Unsafe act and unsafe condition that cause	sed the accident)
Improper execution of trues in the confined and	seen considering weather factors average
Improper execution of tugs in the confined spa	ces, considering weather factors- currents
Indirect cause (write the descriptively job & personal fact	tors that existed)
Veget	
Vessel maneuvering at confined spaces.	
Root cause: (Write Descriptively the root causes)	
(May address lack of planning , lack of standards, lack of com-	npliance etc.)
lack of planning of execution of proper ship's	handling Failure to execute the assist of tugs due to confined
Each of planning of execution of proper still a	manding 1 differe to expecte the assist of tags due to commen
NN. Immediate Action taken.	omorganicu contact, then advise good local agents
NN. Immediate Action taken.  Report the initial notification of the incident on Verify the safety of the crew, the vessel condit Inform the office crisis management and the go	ood local agent verbally initially through telephone
NN. Immediate Action taken.  Report the initial notification of the incident on Verify the safety of the crew, the vessel condit	tion and pollution prevention as necessary pool local agent verbally initially through telephone
NN. Immediate Action taken.  Report the initial notification of the incident on Verify the safety of the crew, the vessel condit Inform the office crisis management and the go	pod local agent verbally initially through telephone  sective Action) Proper planning & positioning of tugs
NN. Immediate Action taken.  Report the initial notification of the incident on Verify the safety of the crew, the vessel condit Inform the office crisis management and the go	pod local agent verbally initially through telephone  sective Action) Proper planning & positioning of tugs

Original . Synergy Copy - vesser File SF-05 Page 3 of 5

Rev.No. 2 7-JUN-16



# INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.)

GROUP For Statistic	s & Analy	sis (Tick appropriate)	
OO. Details of Accident (tick appropriate May be	more than or	ne)	
Collision		Cargo Damage due to Hatch cover leaks	
Fire / Explosion	님	Cargo Damage due to movement of cargo	
Grounding during Navigation		Cargo Damage due to Contamination	
Touching Bottom at Berth		Cargo lost Overboard	
Contact with Shore Objects		Cargo damage due to other causes	
Contact with Ice		Oil Pollution	
Contact with Floating Objects		Pollution caused by Garbage	
Structural Failure of Hull		Pollution due to Chemicals	
Propulsion Failure		Pollution Resulting from Sewage	
Steering Failure		Pollution caused by Hazardous Cargoes	
Other Machinery Failure		Air Pollution due to Smoke	
Mooring Failure		Power Failure	
Explosion / Fire involving cargo		Equipment on Fire	
Explosion -Boiler/Associated Parts		Heavy Weather Damage	
Personnel/ Equipment Contact		Slips/Trips/Falls	
Exposure - Harmful Substances		Pollution Manne / Atmospheric	
Explosion - Others		Others (Specify)	
PP. Direct causes: (lick appropriate May be mor	re than one)		
01 Failure to follow rules and regulations		09. Failure to secure	
02 Failure to use ppe properly		10. Making safety devices inoperative	
		11. Improper position for task	
03 Operating equipment or machinery			
without authority		12. Improper lifting, handling or storage	
04 Incorrect use of equipment or machinery		13 Horseplay/inappropriate behaviour	
05 Using defective equipment or machinery		14 Under the influence of alcohol	
06 Failure to follow repair/maintenance		and/or other drugs	
instructions		15. Sabotage, wilful damage	
07 Incorrect navigation or ship handling		16. Suicide/homicide	[]
08 Failure to warn		17 Other substandard act(s)	L

Original Synergy Cupy vesserFile SF-05

Page 4 of 5

Rev.No 2 7-July-Jó



# INCIDENT REPORTING ACCIDENT / DAMAGE REPORT

Synergy Group

(In case of injury is reported, please use injury reporting form too.)

GROUP For Statistics &	Analys	is (Tick appropriate)	
Unsafe conditions			
18 Inadequate guards or barners		30 Noise or temperature	
19. Inadequate or defective ppe		31. Radiation exposure	
20. Defective equipment, machinery or tools		32. Inadequate ventilation	
21. Hull or structural condition		33. Environmental conditions	
22. Inadequate warning system		34. Out-dated charts, publications and	
23 Adverse weather conditions		other documentation	
24 Adverse sea conditions		35. Bunkers and/or lubricating oils	
		36. Port and berthing facilities	
25. Poor housekeeping		37. Cargo	
26 Congestion or restricted action		38. Other substandard conditions(s)	
27 Inadequate or excess illumination			
28. Fire and explosion hazards		39 Workspace Restrictions	
29 Inadequate / Excessive lighting			
QQ. Indirect Causes (tick appropriate. May be more the	nan one)		
Personal factors			
01 inadequate physical/physiological capability		05. Lack of knowledge	
02 Inadequate mental/psychological capability		06. Lack of skill	
03 Physical or physiological stress		07. Improper motivation	
04. Mental or psychological stress			
Job Factors			
08 Inadequate leadership and/or supervision		12. Inadequate tools and equipment	
09 Inadequate engineering		13. Inadequate work standards	
10 Inadequate purchasing		14. Excessive wear and tear	
	- Land		

# Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Thursday, November 21, 2019 5:46 AM

To: CBSA Operations; NCC / CCN (DFO/MPO); CCG Western Aids to Navigation / Aides à la

Navigation GCC (DFO/MPO); Payne, Stephen; Jourdenais, Marc; Carlow, Theresa; ROC1 /

COR1 (DFO/MPO); ROC1 / COR1 (DFO/MPO); Clinton. Rebeiro@tsb-bst. gc. ca (Clinton.Rebeiro@tsb-bst.gc.ca); PAC Radio Room / Salle de radio PAC (DFO/MPO);

Environment Canada (ec.cnue-neec.ec@canada.ca); Glenn Budden (Glenn.Budden@tsb-bst.gc.ca); Harbour Master - Vancouver; Harbour Master- Victoria ; Harbour Master- Victoria Assistant ; Brady, Jeff; Victoria JRCC [DND]; Carrigan, Kevin; Mcculloch, Lisa; CCG MCTS RHQ Western / GCC SCTM bureau régional lOuest (DFO/MPO); Statham, Art; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca); CCG West MSOC / COSM Ouest GCC (DFO/MPO); Pacific Pilotage Authority (info@ppa.gc.ca); RCMP West Coast Marine Services; Ciammaichella, Rita; Stroud, Chad; Pickrell, Susan; SITCEN [TC]; TC Marine

Safety - Vancouver; TC SITCEN alternate; Transportation Safety Board - Pacific; Zillur.

Rahman@tsb-bst.gc.ca (Zillur.Rahman@tsb-bst.gc.ca)

Cc: Waheed, Israr

**Subject:** FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #2

Attachments: RA Sailing Vessel to discharge port (China) with dent on hul.pdf; Incident Report 20 Nov

19.pdf

Follow Up Flag: Follow up Flag Status: Completed

UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

# Regards

# Israr Waheed

Senior Marine Inspector Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT								
VESSEL NAME/CALL SIGN/REG :								
JRCC INCIDENT #:		V19- PRIORITY: - BROADCAST: -					-	
INCIDENT START TIME:		20/Nov/2019 1638 PST						
INCIDENT END	TIME:	Click here to e	enter a da	ate. Click h	ere to enter	text.		
NATURE OF INCIDENT:		ALLISION						
PERSONS ON BO	OARD:	LOSS OF LIFE: No						
POSITION (GPS / GEOGRAPHIC):		VANCOUVER HARBOUR – ALLIANCE GRAIN EAST 49 17.21.1N 123 04.43.2W						
VESSEL PARTIC	<u>ULARS</u>	1	•					
LOA:	224.94M	TYPE:	BULK C	ARRIER	OFFICIAL#	4003050		
MMSI:	564252000	GRT/DWT:	39738T	LP/76596T	IMO:	9362217		
DESTINATION:	VANCOUVER, BC	LAST PORT:			CARGO:			
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE PTE LTE		SHIP PHONE/S PHONE:	AT		
ADDITIONAL VE	SSEL DETAILS:				·			
SITUATION DET	AILS							
SITREP/RESOLUTION:		DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST.  PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.						
INTENTIONS OF MASTER:								
ON-SCENE ASSISTANCE:								
POLLUTION/NAV HAZARD:		NONE REPORTED						
WEATHER DETA	<u>AILS</u>	,						
VISIBILITY:		GOOD		WIND (KNOTS):		LIGHT		
SEA STATE:		CALM		TIDE/CURRENT:				
ALERT LIST (NAME AND DATE/TIME OF VERBAL ALERT)								
CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCHARGE)								
TC MARINE SAFETY OFFICER		20/Nov/2019 1649 PST						
(COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEL  VANCOUVER HBR MASTER  (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)		20/Nov/2019 1645 PST						
MCTS OFFICER:		JN						

MCTS WATCH SUPERVISOR:

JN

**VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA** 

SUPERVISOR.VICTORIA@INNAV.GC.CA /TEL: 250-363-6333 | 1-800-661-9202 / FAX: 250-363-6556

Rishar as and Oceans Ráchas ar Oceans Canada Canada

Canadian

Carre chiare

Chast Guard

tanasanna



Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

**Victoria Marine Communications & Traffic Services** P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

# Rear, Scott

From: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>

Sent: Thursday, November 28, 2019 2:55 PM

To: Rear, Scott

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

VANCOUVER - ALLISION - UPDATE #3

Attachments: NKK Report 21 Nov 19.pdf

From: Supervisor. Victoria

Sent: Thursday, November 21, 2019 12:38 PM

To: CBSA Operations <953NPCU05G@cbsa-asfc.gc.ca>; CCG National Coordination Centre <NCC-CCN.XNCR@dfompo.gc.ca>; CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-IOuest-GCC.MPO@dfompo.gc.ca) <DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-lOuest-GCC.MPO@dfo-mpo.gc.ca>; CCG-W JRCC A/Supervisor <Stephen.payne@dfo-mpo.gc.ca>; CCG-W Manager Marine Aids Coastal <marc.jourdenais@dfompo.gc.ca>; CCG-W Marine Aids Coastal Officer <theresa.carlow@dfo-mpo.gc.ca>; CCG-W ROC - Alerting <dfo.roc1cor1.mpo@dfo-mpo.gc.ca>; CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca) <roc1cor1@dfo-mpo.gc.ca>; Clinton. Rebeiro@tsb-bst.gc.ca (Clinton.Rebeiro@tsb-bst.gc.ca) <Clinton.Rebeiro@tsb-bst.gc.ca>; DFO Radio Room -Aldergrove <pacradioroomrhq@pac.dfo-mpo.gc.ca>; Environment Canada (ec.cnue-neec.ec@canada.ca) <ec.cnueneec.ec@canada.ca>; Glenn Budden (Glenn.Budden@tsb-bst.gc.ca) < Glenn.Budden@tsb-bst.gc.ca>; Harbour Master -Vancouver <harbour\_master@portmetrovancouver.com>; Harbour Master- Victoria <mariah.mccooey@tc.gc.ca>; Harbour Master-Victoria Assistant <zoe.polden@tc.gc.ca>; Jeff Brady <jeff.brady@dfo-mpo.gc.ca>; JRCC Victoria <jrccvictoria@sarnet.dnd.ca>; Kevin, Carrigan <kevin.carrigan@dfo-mpo.gc.ca>; Lisa McCulloch <lisa.mcculloch@dfo-</p> mpo.gc.ca>; MCTS Regional Office <mcts@dfo-mpo.gc.ca>; MCTS-W REGIONAL SUPERINTENDANT (AS) <a href="mailto:</a></art.Statham@dfo-mpo.gc.ca"><a href="mailto:Mohan.Raman@tsb-bst.gc.ca"><a href="mailto:Moh WEST <MSOC-WEST.XNAT@DFO-MPO.GC.CA>; Pacific Pilotage Authority (info@ppa.gc.ca) <info@ppa.gc.ca>; RCMP West Coast Marine Services < E WCMS RCC.PO5.EDIV1@rcmp-grc.gc.ca>; RITA CIAMMAICHELLA <Rita.Ciammaichella@dfo-mpo.gc.ca>; Stroud, Chad <Chad.Stroud@dfo-mpo.gc.ca>; Sue Pickrell <susan.pickrell@dfompo.gc.ca>; TC Marine Safety - Ottawa <sitcen@tc.gc.ca>; TC Marine Safety - Vancouver <tcmarpac@tc.gc.ca>; TC SITCEN alternate <tc.sitcenhq.centredinterventionac.tc@canada.ca>; Transportation Safety Board - Pacific <MarineNotifications.Pacific@bst-tsb.gc.ca>; Zillur. Rahman@tsb-bst.gc. ca (Zillur.Rahman@tsb-bst.gc.ca) <Zillur.Rahman@tsb-bst.gc.ca>

Subject: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - UPDATE #3

## UPDATE #3 2019/11/21 - 1205PST

Vessel provides CLASS Inspection report, attached, and receives verbal clearance for departure from TCMS Inspector. Awaiting report from TCMS. Vessel currently making preparations for departure from Vancouver to China.

Regards,

**Robert Booth** 

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333

Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V&L 4B2

# UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

# UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

## Israr Waheed

Senior Marine Inspector
Cargo and Examination Services

GENERAL DATA – MARINE OCCURRENCE REPORT						
VESSEL NAME/CALL SIGN/REG :	OCEAN TRADER 1/9V3626					
JRCC INCIDENT #:	V19- PRIORITY: - BROADCAST: -					
INCIDENT START TIME:	20/Nov/2019 1638 PST					
INCIDENT END TIME:	Click here to enter a date. Click here to enter text.					
NATURE OF INCIDENT:	ALLISION					
PERSONS ON BOARD:	LOSS OF LIFE: No					
POSITION (GPS / GEOGRAPHIC):	VANCOUVER HARBOUR – ALLIANCE GRAIN EAST					
	49 17.21.1N 123 04.43.2W					
VESSEL PARTICULARS						

Document Peleased Under the Access to Information Acti/ Document divulgué en ve

LOA:	224.94M	TYPE:	BULK (	CARRIER	OFFICIAL #	‡	4003050	
MMSI:	564252000	GRT/DWT:	39738	TLP/76596T	IMO:	************	9362217	
DESTINATION:	VANCOUVER, BC	LAST PORT:		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	CARGO:			
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE PTE LT	OCEAN D	SHIP PHONE PHONE:	/SAT		
ADDITIONAL VE	SSEL DETAILS:	***************************************	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
SITUATION DET	<u>AILS</u>				4144061840644444			
		DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST.  PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.						
INTENTIONS OF	MASTER:							
ON-SCENE ASSIS	STANCE:				************************			
POLLUTION/NA	V HAZARD:	NONE REPORTED						
WEATHER DETA	<u>ILS</u>	**************	********	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		*******		
VISIBILITY:	•			WIND (KNOTS):		LIGHT		
SEA STATE:		CALM	ALM TIDE/CURRE		ENT:			
ALERT LIST (NA	ME AND DATE/TI	ME OF VERBAL	ALERT)					
CCG-W ER DUTY OF (IF POLLUTION PRESENT OR F								
TC MARINE SAFETY OFFICER		20/Nov/20	20/Nov/2019 1649 PST					
(COMMERCIAL VESSEL ONLY OR LOSS OF LIFE ON ANY VESSEL)  VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)			20/Nov/2019 1645 PST					
MCTS OFFICER:		JN	JN					
MCTS WATCH S	JN	JN						
VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES  CANADIAN COAST GUARD/GOVERNMENT OF CANADA  SUPERVISOR.VICTORIA@INNAV.GC.CA /TEL: 250-363-6333   1-800-661-9202 / FAX: 250-363-6556								
Canada Canada Casa Casa		© Canada				<b>®</b> Canadä		

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000

9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

# Rear, Scott

From:

Supervisor.Victoria < Supervisor.Victoria@innav.gc.ca>

Sent:

Thursday, November 28, 2019 2:56 PM

To:

Rear, Scott

Subject:

FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST,

**VANCOUVER - ALLISION - FINAL** 

From: Supervisor. Victoria

Sent: Thursday, November 21, 2019 12:43 PM

To: CBSA Operations <953NPCU05G@cbsa-asfc.gc.ca>; CCG National Coordination Centre <NCC-CCN.XNCR@dfompo.gc.ca>; CCG-W Aids to Navigation (DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-IOuest-GCC.MPO@dfompo.gc.ca) <DFO.CCG-Western-AidstoNavigation-AidesalaNavigation-lOuest-GCC.MPO@dfo-mpo.gc.ca>; CCG-W JRCC A/Supervisor <Stephen.payne@dfo-mpo.gc.ca>; CCG-W Manager Marine Aids Coastal <marc.jourdenais@dfompo.gc.ca>; CCG-W Marine Aids Coastal Officer <theresa.carlow@dfo-mpo.gc.ca>; CCG-W ROC - Alerting <dfo.roc1cor1.mpo@dfo-mpo.gc.ca>; CCG-W ROC - OPERATIONS (roc1cor1@dfo-mpo.gc.ca) <roc1cor1@dfo-mpo.gc.ca>; Clinton. Rebeiro@tsb-bst.gc.ca (Clinton.Rebeiro@tsb-bst.gc.ca) < Clinton.Rebeiro@tsb-bst.gc.ca>; DFO Radio Room -Aldergrove <pacradioroomrhq@pac.dfo-mpo.gc.ca>; Environment Canada (ec.cnue-neec.ec@canada.ca) <ec.cnueneec.ec@canada.ca>; Glenn Budden (Glenn.Budden@tsb-bst.gc.ca) < Glenn.Budden@tsb-bst.gc.ca>; Harbour Master -Vancouver <harbour\_master@portmetrovancouver.com>; Harbour Master- Victoria <mariah.mccooey@tc.gc.ca>; Harbour Master-Victoria Assistant <zoe.polden@tc.gc.ca>; Jeff Brady <jeff.brady@dfo-mpo.gc.ca>; JRCC Victoria <irccvictoria@sarnet.dnd.ca>; Kevin, Carrigan <kevin.carrigan@dfo-mpo.gc.ca>; Lisa McCulloch <lisa.mcculloch@dfo-</p> mpo.gc.ca>; MCTS Regional Office <mcts@dfo-mpo.gc.ca>; MCTS-W REGIONAL SUPERINTENDANT (AS) <Art.Statham@dfo-mpo.gc.ca>; Mohan Raman (Mohan.Raman@tsb-bst.gc.ca) <Mohan.Raman@tsb-bst.gc.ca>; MSOC WEST <MSOC-WEST.XNAT@DFO-MPO.GC.CA>; Pacific Pilotage Authority (info@ppa.gc.ca) <info@ppa.gc.ca>; RCMP West Coast Marine Services <E\_WCMS\_RCC.PO5.EDIV1@rcmp-grc.gc.ca>; RITA CIAMMAICHELLA <Rita.Ciammaichella@dfo-mpo.gc.ca>; Stroud, Chad <Chad.Stroud@dfo-mpo.gc.ca>; Sue Pickrell <susan.pickrell@dfompo.gc.ca>; TC Marine Safety - Ottawa <sitcen@tc.gc.ca>; TC Marine Safety - Vancouver <tcmarpac@tc.gc.ca>; TC SITCEN alternate <tc.sitcenhq.centredinterventionac.tc@canada.ca>; Transportation Safety Board - Pacific <MarineNotifications.Pacific@bst-tsb.gc.ca>; Zillur. Rahman@tsb-bst. gc. ca (Zillur.Rahman@tsb-bst.gc.ca) <Zillur.Rahman@tsb-bst.gc.ca>

Subject: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION - FINAL

## FINAL UPDATE 2019/11/21 - 1240PST

Please see the final report from TCMS, attached immediately below.

----Original Message-----

From: lonescu, lon [mailto:ion.ionescu@tc.gc.ca] Sent: Thursday, November 21, 2019 12:31 PM

To: Supervisor.Victoria <Supervisor.Victoria@innav.gc.ca>; Supervisor.Rupert <Supervisor.Rupert@innav.gc.ca>

Cc: Wilson, John < John. Wilson@tc.gc.ca>; Rushwan, Al <al.rushwan@tc.gc.ca>; Waheed, Israr

<israr.waheed@tc.gc.ca>; Sitcen HQ / Centre d'intervention AC (TC) <TC.SitcenHQ-

CentredinterventionAC.TC@tc.gc.ca>; colley@colleywest.bc.ca; 'oceantrader1@amosconnect.com'

<oceantrader1@amosconnect.com>

Subject: FW: 1480-2019-MOR-VIC-OCEAN TRADER 1/9V3626 - ALLIANCE GRAIN EAST, VANCOUVER - ALLISION -

UPDATE #2
Importance: High

Transport Canada Marine Safety Inspector Ion Ionescu gives the following Instructions:

• The Class Report has been received and reviewed. No further restrictions. The vessel is cleared to sail.

The Master is fully responsible for the safety of the vessel and should only proceed if the Master considers it is safe to do so.

All communications and rectification reports to be sent to MCTS.

# Capt. ION IONESCU

Senior Marine Inspector, Compliance & Enforcement and Cargo Services Transport Canada / Government of Canada ion.ionescu@tc.gc.ca / Tel: 604-666-4200 / TTY: 1-888-675-6863

Inspecteur Maritime Principal, Conformité & application des règlements et services de marchandises Transports Canada / Gouvernement du Canada ion.ionescu@tc.gc.ca / Tél: 604-666-4200 / ATS: 1-888-675-6863

# Regards,

Robert Booth

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2

# UPDATE #3 2019/11/21 - 1205PST

Vessel provides CLASS Inspection report, attached, and receives verbal clearance for departure from TCMS Inspector. Awaiting report from TCMS. Vessel currently making preparations for departure from Vancouver to China.

# UPDATE #2 2019/11/21 03:52 PST

Duly received mail, well noted. Please see the remarks that follows as per below queries.

Kindly acknowledge safe receipt.

Thank you.

Best regards, Capt. Alex F. Azares Master M/V Ocean Trader I

# UPDATE #1 2019/11/20 18:05 PST

Please forward the following instructions to the master:

- Master to confirm there is no ingress of water through hull.
- Provide incident report including risk assessment.

Master is fully responsible for safety and safe operation of the vessel at all times and only proceeds if it is safe to do so.

All communications and rectification report to be sent to MCTS.

Regards

## Israr Waheed

Senior Marine Inspector Cargo and Examination Services

GENERAL DATA	- MARINE OCCU	RRENCE REPOR	<u>T</u>		Alah ,			
VESSEL NAME/CALL SIGN/REG :		OCEAN TRADER 1/9V3626						
JRCC INCIDENT #:		V19-	PRIORITY:	- B	ROADCAST:	-		
INCIDENT START TIME:		20/Nov/2019 1638 PST						
INCIDENT END TIME:		Click here to enter a date. Click here to enter text.						
NATURE OF INCIDENT:		ALLISION						
PERSONS ON BOARD:		LOSS OF LIFE: No						
POSITION (GPS / GEOGRAPHIC):		VANCOUVER HARBOUR – ALLIANCE GRAIN EAST 49 17.21.1N 123 04.43.2W						
VESSEL PARTIC	<u>ULARS</u>							
LOA:	224.94M	TYPE:	BULK CARRIER	OFFICIAL#	4003050			
MMSI:	564252000	GRT/DWT:	39738TLP/76596T	імо:	9362217			
DESTINATION:	VANCOUVER, BC	LAST PORT:		CARGO:				
FLAG:	SINGAPORE	OWNER/ AGENT CONTACT:	GRACE OCEAN PTE LTD	SHIP PHONE/SA PHONE:	AT .			
ADDITIONAL VE	SSEL DETAILS:							
SITUATION DET	<u> AILS</u>							
SITREP/RESOLUTION:		DIRECTOR OF PACIFIC COAST PILOTS CALLED TO REPORT THAT THE OCEAN TRADER 1 COLLIDED WITH THE DOCK WHEN BERTHING AT ALLIANCE GRAIN EAST.						

	•	PILOT REPORTS HULL SUSTAINED A DENT AND THE PADDING ON THE BERTH WAS DAMAGED. SHIP OTHERWISE IN GOOD CONDITION.					
INTENTIONS OF MASTE	R:						
ON-SCENE ASSISTANCE							
POLLUTION/NAV HAZA	RD: N	ONE REPORTED					
WEATHER DETAILS							
VISIBILITY:	ISIBILITY: GOOD		WIND (KNOTS):	LIGHT			
SEA STATE:	C/	ALM	TIDE/CURRENT:				
ALERT LIST (NAME ANI	DATE/TIME	OF VERBAL ALERT					
CCG-W ER DUTY OFFICER (IF POLLUTION PRESENT OR RISK OF DISCH							
TC MARINE SAFETY OFFICER (COMMERCIAL VESSEL ONLY OR LOSS OF L		20/Nov/2019 1649 PST					
VANCOUVER HBR MASTER (ONLY IF WITHIN OR BOUND FOR VANCOUVER HARBOUR)		20/Nov/2019 1645 PST					
MCTS OFFICER:		JN					
MCTS WATCH SUPERVISOR:		JN					
VICTORIA MARINE COMMUNICATIONS AND TRAFFIC SERVICES CANADIAN COAST GUARD/GOVERNMENT OF CANADA <u>SUPERVISOR.VICTORIA@INNAV.GC.CA</u> /TEL: 250-363-6333   1-800-661-9202 / FAX: 250-363-6556							
Signal as and Oceans Canada	Páchas ar Oceans Canada			٠			
Sanaziai Sanaziai	Garan chi a wa tanada ma	Canadä					

Shift Supervisor - Victoria MCTS Centre

Telephone: 250-363-6333 Facsimile: 250-363-6556

Supervisor.Victoria@innav.gc.ca

Victoria Marine Communications & Traffic Services P.O. Box 6000 9860 West Saanich Road Sidney, BC, Canada, V8L 4B2